

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Kaliori - Kendalisada



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 6 M
CATATAN : SEDANG

LOKASI : STA 0+200

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 6 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	Kaliori - Kendalisada		KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Kaliori - Kendalisada



LOKASI : STA 0+400

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 4 M
CATATAN : RUSAK BERAT

LOKASI : STA 0+600

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 4 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	Kaliori - Kendalisada		KHOLID - SANDI	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Kaliori - Kendalisada



LOKASI : STA 0+800

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 4 M
CATATAN : RUSAK BERAT

LOKASI : STA 1+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 4 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	Kaliori - Kendalisada		KHOLID - SANDI	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Kaliori - Kendalisada



LOKASI : STA 1+200

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 4 M
CATATAN : RUSAK BERAT


LOKASI : STA 1+400 - 1+525

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 4 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	Kaliori - Kendalisada		KHOLID - SANDI	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Kaliori - Kendalisada



LOKASI : **STA** **1+525** - **1+550**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	Kaliori - Kendalisada		KHOLID - SANDI	3