

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK RINGAN

LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : BAIK

LOKASI : STA 0+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 0+800

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : BAIK

LOKASI : STA 1+000

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 1+200

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : BAIK

LOKASI : STA 1+400

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3-4 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	4

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 1+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : BAIK



LOKASI : STA 1+800

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	5

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 2+000

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT




LOKASI : STA 2+200

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	6

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 2+400

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT

LOKASI : STA 2+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	7

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 2+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK RINGAN

LOKASI : STA 3+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	8

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 3+200

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT



LOKASI : STA 3+400

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	9

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 3+600

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT



LOKASI : STA 3+800

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	10

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 4+000

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK BERAT

LOKASI : STA 4+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	11

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Pancasan (Guwalangu) - Sawangan



LOKASI : STA 4+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : SEDANG

LOKASI : STA 4+550

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3-4 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
17	Pancasan (Guwalangu) - Sawangan		KHOLID - SANDI	12