

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

LOKASI : STA 0+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	2


FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 0+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG



LOKASI : STA 1+000

KONDISI PERKERASAN : KERIKIL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK BERAT

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	3

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 1+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN



LOKASI : STA 1+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	4


FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 1+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN



LOKASI : STA 1+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	5

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 2+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 2+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	6

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 2+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 2+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	7

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 2+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG




LOKASI : STA 3+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	8

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : **STA 3+200**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

LOKASI : **STA 3+400**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	9

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : **STA 3+600**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN

LOKASI : **STA 3+800**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	10

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 4+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN



LOKASI : STA 4+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : RUSAK RINGAN

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	11

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 4+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG



LOKASI : STA 4+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	12

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 4+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 5+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	13

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 5+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 5+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	14

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 5+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG



LOKASI : STA 5+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	15

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 6+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 6+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	16

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 6+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 6+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	17

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 6+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 7+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	18

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 7+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 7+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	19

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 7+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 7+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	20

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : **STA** **8+000**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3,5 M

CATATAN : BAIK



LOKASI : **STA** **8+200**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3,5 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	21

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : **STA** **8+400**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3,5 M

CATATAN : BAIK



LOKASI : **STA** **8+600**

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 3,5 M

CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	22

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : **STA 8+800**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : **STA 9+000**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	23

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : **STA 9+200**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : **STA 9+400**

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	24

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 9+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 9+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	25

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 10+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK





LOKASI : STA 10+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	26

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 10+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

LOKASI : STA 10+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	27

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 10+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

LOKASI : STA 11+000

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	28

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 11+200

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 11+400

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	29

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Cibangkong - Cihonje



LOKASI : STA 11+600

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK



LOKASI : STA 11+800

KONDISI PERKERASAN : ASPAL
LEBAR PERKERASAN : 3,5 M
CATATAN : BAIK

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG	PETUGAS SURVEY	HALAMAN
277	Cibangkong - Cihonje	KABUPATEN BANYUMAS	KODHI - REZA	30