

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Kedondong - Sokaraja Kulon



LOKASI : STA 0+000

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : BAIK

LOKASI : STA 0+200

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
513	Kedondong - Sokaraja Kulon		KHOLID - SANDI	1

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Kedondong - Sokaraja Kulon



LOKASI : STA 0+400

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : SEDANG

LOKASI : STA 0+600

KONDISI PERKERASAN : ASPAL

LEBAR PERKERASAN : 4 M

CATATAN : SEDANG

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
513	Kedondong - Sokaraja Kulon		KHOLID - SANDI	2

FOTO SURVEY KONDISI JALAN TAHUN 2020

RUAS JALAN : Kedondong - Sokaraja Kulon



LOKASI : **STA 0+800**

KONDISI PERKERASAN : **ASPAL**

LEBAR PERKERASAN : **4 M**

CATATAN : **BAIK**

LOKASI : **STA 0+920**

KONDISI PERKERASAN : **ASPAL**

LEBAR PERKERASAN : **3 M**

CATATAN : **SEDANG**

NO. RUAS	NAMA RUAS	DPU & PENATAAN RUANG KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
513	Kedondong - Sokaraja Kulon		KHOLID - SANDI	3