

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 0+000**

KONDISI PERKERASAN : BAIK
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

LOKASI : **STA 0+100**

KONDISI PERKERASAN : BAIK
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	1

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 0+200**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

LOKASI : **STA 0+300**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	2

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 0+400**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

LOKASI : **STA 0+500**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	3

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 0+600**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

LOKASI : **STA 0+700**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	4

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 0+800**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

LOKASI : **STA 0+900**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	5

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 1+000**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

LOKASI : **STA 1+100**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	6

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 1+200**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL



LOKASI : **STA 1+300**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	7

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 1+400**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL



LOKASI : **STA 1+500**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	8

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 1+600**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL



LOKASI : **STA 1+700**

KONDISI PERKERASAN : RUSAK RINGAN
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	9

FOTO SURVEY KONDISI JALAN TAHUN 2022

RUAS JALAN : Kalibagor PDAM -Pekaja



LOKASI : **STA 1+800**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 2.8 M
CATATAN : ASPAL



LOKASI : **STA 1+860**

KONDISI PERKERASAN : SEDANG
LEBAR PERKERASAN : 3 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
133	Kalibagor PDAM -Pekaja		YANU & INDRA	10