

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 0+000

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 10 M

CATATAN : Aspal

LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 8 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			1

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 0+200

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			2

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 0+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+470

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			3

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 0+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+580

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			3

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+635

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			4

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 0+653

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+700

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			4

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 0+800

LOKASI : STA 0+827

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			5

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 0+900

LOKASI : STA 1+000

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			6

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 1+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal



LOKASI : STA 1+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			7

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 1+300

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
CATATAN : Aspal



LOKASI : STA 1+400

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			8

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



8 Okt 2024 9:37:26 AM
7,493050S 109,286948E
Kabupaten Banyumas
#NO RUAS 143
#Survey SDI & RNI #DPU Kab. Banyumas #1+500



8 Okt 2024 9:37:59 AM
7,494192S 109,287354E
Kabupaten Banyumas
#NO RUAS 143
#Survey SDI & RNI #DPU Kab. Banyumas #1+600

LOKASI : STA 1+500

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

LOKASI : STA 1+600

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			9

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



8 Okt 2024 9:38:40 AM
7,489922S 109,284930E
Kabupaten Banyumas
#NO RUAS 143
#Survey SDI & RNI #DPU Kab. Banyumas #1+700



8 Okt 2024 9:39:18 AM
7,489902S 109,284008E
Kabupaten Banyumas
#NO RUAS 143
#Survey SDI & RNI #DPU Kab. Banyumas #1+800

LOKASI : STA 1+700

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

LOKASI : STA 1+800

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			10

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



8 Okt 2024 9:39:54 AM
7,489577S 109,282812E
Kabupaten Banyumas
#NO RUAS 143
#Survey SDI & RNI #DPU Kab. Banyumas #1+900



8 Okt 2024 9:40:23 AM
7,489593S 109,282323E
Kabupaten Banyumas
#NO RUAS 143
#Survey SDI & RNI #DPU Kab. Banyumas #2+000

LOKASI : STA 1+900

LOKASI : STA 2+000

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			11

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



8 Okt 2024 9:41:10 AM
7,489980S 109,281192E
Kabupaten Banyumas
#NO RUAS 143
#Survey SDI & RNI #DPU Kab. Banyumas #2+100



8 Okt 2024 9:41:44 AM
7,490293S 109,280838E
Kabupaten Banyumas
#NO RUAS 143
#Survey SDI & RNI #DPU Kab. Banyumas #2+200

LOKASI : STA 2+100

LOKASI : STA 2+200

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

KONDISI PERKERASAN : Baik


LEBAR PERKERASAN : 5 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			12

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENDALISADA - TPST



LOKASI : STA 2+310

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
143	KENDALISADA - TPST			13