

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENITEN - DAWUHAN WETAN



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
201	KENITEN - DAWUHAN WETAN			1

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENITEN - DAWUHAN WETAN



LOKASI : STA 0+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
201	KENITEN - DAWUHAN WETAN			2

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : KENITEN - DAWUHAN WETAN



LOKASI : STA 0+400

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

LOKASI : STA 0+450

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
201	KENITEN - DAWUHAN WETAN			3