

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. BRIGJENT. ENCUNG



LOKASI :	STA	0+000	LOKASI :	STA	0+100
KONDISI PERKERASAN	:	Sedang	KONDISI PERKERASAN	:	Rusak Ringan
LEBAR PERKERASAN	:	6 M	LEBAR PERKERASAN	:	5 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	
471	JL. BRIGJENT. ENCUNG			1	

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. BRIGJENT. ENCUNG



LOKASI :	STA	0+200	LOKASI :	STA	0+300
KONDISI PERKERASAN	:	Sedang	KONDISI PERKERASAN	:	Sedang
LEBAR PERKERASAN	:	5 M	LEBAR PERKERASAN	:	5 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	
471	JL. BRIGJENT. ENCUNG			2	

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. BRIGJENT. ENCUNG



LOKASI :	STA	0+400	LOKASI :	STA	0+500
KONDISI PERKERASAN	:	Sedang	KONDISI PERKERASAN	:	Baik
LEBAR PERKERASAN	:	5 M	LEBAR PERKERASAN	:	5 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	
471	JL. BRIGJENT. ENCUNG			3	

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. BRIGJENT. ENCUNG



LOKASI :	STA	0+600	LOKASI :	STA	0+700
KONDISI PERKERASAN	:	Rusak Ringan	KONDISI PERKERASAN	:	Rusak Ringan
LEBAR PERKERASAN	:	5 M	LEBAR PERKERASAN	:	5 M
CATATAN	:	Aspal	CATATAN	:	Aspal
NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN	
471	JL. BRIGJENT. ENCUNG			4	

FOTO SURVEY KONDISI JALAN TAHUN 2024

RUAS JALAN : JL. BRIGJENT. ENCUNG



LOKASI : STA 0+800

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 5 M

CATATAN : Aspal

LOKASI : STA 0+880

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 6 M

CATATAN : Aspal

NO. RUAS	NAMA RUAS	DPU KABUPATEN BANYUMAS	PETUGAS SURVEY	HALAMAN
471	JL. BRIGJENT. ENCUNG			5